



If problem persist after modification applied, then problem was not in aperture command interpretation or modification SW is not compatible or modification was not applied properly.